

CAUTION: Avoid contact with eyes.
Do not ingest or inhale.
Avoid prolonged skin contact.

FIRST AID

Ingestion: If conscious and alert, drink two glasses of water. Do not induce vomiting. Consult a physician.

Eyes and Skin: Flush with water for 15 minutes.

Inhalation: Remove to fresh air.
If any irritation persists, seek medical attention.

PRECAUCION: Evite el contacto con los ojos.
No ingiera o inhale.

Evite el contacto prolongado con la piel.

PRIMEROS AUXILIOS

Ingestión: Si se encuentra consciente y alerta, tome dos vasos de agua. No induzca el vomito. Consulte con un medico.

Ojos y Piel: Lave con abundante agua por 15 minutos.

Inhalación: Remuevase a un lugar con aire fresco.

Si cualquier irritacion persiste, busque atencion medica.

5 Gallons _____ Gallons

1 Gallon (3.8 Liters) (unless checked otherwise)

ULTRATHANE

#9662

Urethane Fortified Floor Finish & Sealer

Durable, High Gloss & Self-Shining,
With Or Without High Speed Buffing

Read Material Safety Data Sheet Carefully Before Handling.

Lea Cuidadosamente La Hoja De Datos
Para La Seguridad Del Material Antes Del Manejar.

For Commercial & Industrial Use Only

Keep Away From Children

Solamente Para El Uso Comercial Y Industrial
Mantengalo Lejos Del Alcance De Los Niños

ARCOT
MANUFACTURING CORPORATION

www.ArcotManufacturing.com

2950 Mowery Road, Houston, Texas 77045 (713) 413-9700

ULTRATHANE is a urethane fortified floor finish which uses the finest of polymers for gloss, buffing ability, removability and black mark resistance. These features are combined with the wear and soil resistance, clarity and flexibility of urethane. These features give ULTRATHANE top performance and makes it the finish of choice in programs which deal with high traffic and where regular recoating is not practical.

APPLICATION

Prepare the floor carefully. Proper preparation will assure the finest appearance consistent with the time and materials invested.

Remove the old floor wax/finish thoroughly and completely with a heavy duty stripper, black pad and machine. Rinse with clear water, remove water and dry. Test floor to ensure that neither old wax nor stripper, even residual amounts, is left. If necessary, repeat stripping and/or cleaning steps.

Apply 1 coat of sealer undercoat and allow to dry for 45 minutes. If preferred, this product is durable enough to use as a sealer. Apply 2-3 coats of ULTRATHANE using a new, lint-free, rayon mop, allowing 20-30 minutes between coats. If no sealer/undercoater is used, apply 4-5 coats. Do not buff for 24 hours. Buffing sooner may cause crazing of the finish and result in shorter life, less gloss and possible powdering.

For extra gloss and longer wear, allow floor to dry overnight, then apply two additional coats.